


Monitor plus Software EC 11



EC 11 is a data monitoring software monitoring instruments such as ovens and laboratories for temperature and humidity.

In the software it is possible to set alarm limits.

The software has three main windows, one to see actual temperature values and corresponding curves, one for comparing historical data and one setting the communication with the amplifiers.

Sensors for temperature, humidity, pressure, displacement, V, mA etc are connected to a data box with amplifiers. Each data box can have 1 to 24 inputs for different sensors. One or more data boxes are connected via a network connection to a computer running the Monitor Plus software. Several data boxes can be situated in different rooms and be connected to the logging computer via the company network.

EC 11.01 is a Viewer software making it possible to view the results from any computer in the network.